

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
0		Good condition Slight pitting to the rails	Good condition	Good condition	Track marked out with back to Douglas, Left Hand Rail and Right Hand Rail. Switches in this section				
50		Good condition Slight pitting to the rails	Good condition	Good condition					
100		Good condition Slight pitting to the rails	Good condition	Good condition					
150		Good condition Slight pitting to the rails	Good condition	Good condition	Switches in this section				
200		Good condition Slight pitting to the rails	Good condition	Good condition	Switches in this section. 3 tie bars have been fitted in this section				
250		Good condition Slight pitting to the rails	Good condition	Good condition	Switches in this section				
300		Good condition Slight pitting to the rails	Good condition	Good condition	3 tie bars have been fitted in this section				
350		Good condition, rail foot covered by ballast	Good condition, covered by ballast	Good condition	Switches in this section				
400		Good condition Slight pitting to the rails	Fair condition	Good condition					
450		Good condition Slight pitting to the rails	Fair condition	Fair condition, ballast low, sleeper ends exposed.					
500		Good condition Slight pitting to the rails	Fair condition	Fair condition, ballast low, sleeper ends exposed.					
550		Good condition Slight pitting to the rails	Fair condition	Fair condition, ballast low, sleeper ends exposed.					
600		Good condition Slight pitting to the rails	Fair condition	Fair condition, ballast low, sleeper ends exposed.					
650		Good condition Slight pitting to the rails	Fair condition, where visible, covered by ballast	Fair condition, ballast low, sleeper ends exposed.					
700		Good condition Slight pitting to the rails	Good condition	Fair condition.					
750	Underbridge	Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.	Left Hand Curve, 8 tie bars fitted around the curve, gauge varies around the curve where the tie bars are fitted.				
800		Good condition Slight pitting to the rails	Good condition	Fair condition.					
850		Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.					
900		Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.					
950		Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.					
1000		Good condition Slight pitting to the rails	Good condition	Poor condition, contaminated with fines, moss growing on the ballast, ballast low, sleeper ends exposed.					
1050		Good condition Slight pitting to the rails	Good condition	Fair condition, contaminated with fines, moss growing on the ballast, ballast low, sleeper ends exposed.	Left Hand Curve				
1100		Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.					
1150		Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.	Straight				
1200		Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.	Right Hand Curve				
1250		Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.					
1300	Underbridge	Good condition Slight pitting to the rails	Good condition	Fair condition, ballast low, sleeper ends exposed.	Right Hand Curve ends				
1350		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
1400		Good condition Slight pitting to the rails	Good condition	Good condition, sleeper ends exposed					
1450		Good condition Slight pitting to the rails	Good condition	Good condition					
1500		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
1550	Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
1600		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
1650		Good condition Slight pitting to the rails	Good condition	Good condition					
1700		Good condition Slight pitting to the rails	Good condition	Good condition					
1750		Good condition Slight pitting to the rails	Good condition	Good condition					
1800		Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
1850		Good condition Slight pitting to the rails	Good condition	Good condition, sleeper ends exposed					
1900	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
1950		Good condition Slight pitting to the rails	Good condition	Fair condition					
2000	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Fair condition					
2050		Good condition Slight pitting to the rails	Good condition	Good condition					
2100		Good condition Slight pitting to the rails	Good condition	Good condition					
2150		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
2200		Good condition Slight pitting to the rails	Good condition	Good condition					
2250		Good condition Slight pitting to the rails	Good condition	Good condition					
2300		Good condition Slight pitting to the rails	Good condition	Good condition					
2350		Good condition Slight pitting to the rails	Good condition	Good condition					
2400	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
2450		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
2500		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
2550		Good condition Slight pitting to the rails	Good condition	Good condition					
2600		Good condition Slight pitting to the rails	Good condition	Good condition					
2650	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
2700		Good condition Slight pitting to the rails	Good condition	Good condition					
2750		Good condition Slight pitting to the rails	Good condition	Good condition					
2800		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
2850		Good condition Slight pitting to the rails	Good condition	Good condition					
2900		Good condition Slight pitting to the rails	Good condition	Good condition					
2950		Good condition Slight pitting to the rails	Good condition	Good condition					
3000		Good condition Slight pitting to the rails	Fair condition	Good condition, sleeper ends exposed					
3050		Good condition Slight pitting to the rails	Fair condition	Good condition, sleeper ends exposed					
3100		Good condition Slight pitting to the rails	Fair condition	Fair condition, sleeper ends exposed					
3150	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition, sleeper ends exposed					
3200		Good condition Slight pitting to the rails	Good condition	Good condition, sleeper ends exposed					
3250		Good condition Slight pitting to the rails	Good condition	Good condition, sleeper ends exposed	Gauge 1/2" wide				
3300		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
3350		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
3400		Good condition Slight pitting to the rails	Good condition	Good condition					
3450		Good condition Slight pitting to the rails	Good condition	Good condition					
3500		Good condition Slight pitting to the rails	Good condition	Good condition					
3550		Good condition Slight pitting to the rails	Good condition	Good condition					
3600		Good condition Slight pitting to the rails	Good condition	Good condition					
3650		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
3700		Good condition Slight pitting to the rails	Fair condition	Fair / Poor condition contaminated with fines and vegetation					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
3750		Good condition Slight pitting to the rails	Fair condition	Fair / Poor condition contaminated with fines and vegetation	Tie bar fitted in this section. Photograph 162				
3800	Underbridge	Good condition Slight pitting to the rails	Fair condition	Fair / Poor condition contaminated with fines and vegetation	Gauge 1/2" wide Poor top either side of the underbridge				
3850		Good condition Slight pitting to the rails	Good condition	Good condition					
3900		Good condition Slight pitting to the rails	Good condition	Good condition					
3950		Good condition Slight pitting to the rails	Fair condition	Good condition					
4000		Good condition Slight pitting to the rails	Fair condition	Good condition					
4050		Good condition Slight pitting to the rails	Fair condition	Good condition	Straight				
4100		Good condition Slight pitting to the rails	Good condition	Good condition					
4150		Good condition Slight pitting to the rails	Good condition	Good condition					
4200		Good condition Slight pitting to the rails	Good condition	Good condition					
4250		Good condition Slight pitting to the rails	Good condition	Good condition					
4300		Good condition Slight pitting to the rails	Good condition	Good condition					
4350		Good condition Slight pitting to the rails	Good condition	Good condition					
4400	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
4450		Good condition Slight pitting to the rails	Good condition	Good condition					
4500		Good condition Slight pitting to the rails	Good condition	Good condition					
4550		Good condition Slight pitting to the rails	Good condition	Good condition					
4600		Good condition Slight pitting to the rails	Good condition	Good condition					
4650		Good condition Slight pitting to the rails	Good condition	Good condition					
4700		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
4750	Overbridge	Good condition Slight pitting to the rails	Fair condition	Poor condition contaminated with fines and vegetation	Left Hand Curve Tie bars fitted in this section				
4800		Good condition Slight pitting to the rails	Fair condition	Poor condition contaminated with fines and vegetation	Left Hand Curve Tie bars fitted in this section				
4850		Good condition Slight pitting to the rails	Fair condition	Fair condition contaminated with fines and vegetation	Left Hand Curve Tie bars fitted in this section				
4900		Good condition Slight pitting to the rails	Fair condition	Fair condition contaminated with fines and vegetation	Left Hand Curve Tie bars fitted in this section				
4950		Good condition Slight pitting to the rails	Fair condition	Fair Condition	Straight Switch & Crossing in this section				
5000		Good condition Slight pitting to the rails	Good condition	Good condition	Port Soderick Station				
5050		Good condition Slight pitting to the rails	Good condition	Good condition					
5100		Good condition Slight pitting to the rails	Good condition	Good condition					
5150		Good condition Slight pitting to the rails	Good condition	Good condition					
5200		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
5250		Good condition Slight pitting to the rails	Good condition	Good condition					
5300		Good condition Slight pitting to the rails	Good condition	Good condition					
5350		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
5400		Good condition Slight pitting to the rails	Good condition	Good condition					
5450		Good condition Slight pitting to the rails	Good condition	Good condition					
5500		Good condition Slight pitting to the rails	Good condition	Good condition					
5550		Good condition Slight pitting to the rails	Good condition	Good condition					
5600	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
5650		Good condition Slight pitting to the rails	Good condition	Good condition					
5700		Good condition Slight pitting to the rails	Good condition	Good condition					
5750	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
5800		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
5850		Good condition Slight pitting to the rails	Good condition	Good condition					
5900		Good condition Slight pitting to the rails	Good condition	Good condition					
5950		Good condition Slight pitting to the rails	Good condition	Good condition					
6000	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
6050		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
6100		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
6150		Good condition Slight pitting to the rails	Good condition	Good condition					
6200		Good condition Slight pitting to the rails	Good condition	Good condition					
6250		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
6300		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
6350		Good condition Slight pitting to the rails	Good condition	Good condition					
6400		Good condition Slight pitting to the rails	Good condition	Good condition					
6450		Good condition Slight pitting to the rails	Good condition	Good condition					
6500		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
6550		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
6600	Overbridge	Good condition Slight pitting to the rails	Fair condition	Good condition	Gauge 1/2" wide				
6650		Good condition Slight pitting to the rails	Fair condition	Good condition					
6700		Good condition Slight pitting to the rails	Fair condition	Good condition	Tie Bar fitted				
6750		Good condition Slight pitting to the rails	Fair condition	Good condition	Tie Bars fitted				
6800		Good condition Slight pitting to the rails	Fair condition	Good condition	Tie Bars fitted Straight				
6850		Good condition Slight pitting to the rails	Good condition	Good condition					
6900	Overbridge 9	Good condition Slight pitting to the rails	Good condition	Fair condition	New sleepers being installed				
6950		Good condition Slight pitting to the rails	Good condition	Good condition	New sleepers being installed				
7000		Good condition Slight pitting to the rails	Good condition	Good condition	New sleepers being installed				
7050		Good condition Slight pitting to the rails	Good condition	Good condition	New sleepers being installed				
7100		Good condition Slight pitting to the rails	Good condition	Good condition	New sleepers being installed				
7150		Good condition Slight pitting to the rails	Good condition	Good condition	New sleepers being installed				
7200		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
7250	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
7300		Good condition Slight pitting to the rails	Good condition	Good condition					
7350		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
7400		Good condition Slight pitting to the rails	Good condition	Good condition					
7450		Good condition Slight pitting to the rails	Good condition	Good condition					
7500	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
7550		Good condition Slight pitting to the rails	Good condition	Good condition					
7600		Good condition Slight pitting to the rails	Good condition	Good condition					
7650		Good condition Slight pitting to the rails	Good condition	Good condition					
7700		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
7750		Good condition Slight pitting to the rails	Good condition	Good condition					
7800		Good condition Slight pitting to the rails	Good condition	Good condition					
7850		Good condition Slight pitting to the rails	Good condition	Good condition					
7900		Good condition Slight pitting to the rails	Good condition	Good condition					
7950	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
8000		Good condition Slight pitting to the rails	Good condition	Good condition					
8050		Good condition Slight pitting to the rails	Good condition	Good condition					
8100		Good condition Slight pitting to the rails	Good condition	Good condition					
8150		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
8200	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
8250		Good condition Slight pitting to the rails	Good condition	Good condition					
8300		Good condition Slight pitting to the rails	Good condition	Good condition					
8350		Good condition Slight pitting to the rails	Good condition	Good condition					
8400		Good condition Slight pitting to the rails	Good condition	Good condition					
8450		Good condition Slight pitting to the rails	Good condition	Good condition					
8500		Good condition Slight pitting to the rails	Good condition	Good condition					
8550	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
8600		Good condition Slight pitting to the rails	Good condition	Good condition					
8650		Good condition Slight pitting to the rails	Good condition	Good condition					
8700		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve Water laying in the cess				
8750		Good condition Slight pitting to the rails	Good condition	Good condition					
8800		Good condition Slight pitting to the rails	Good condition	Good condition					
8850		Good condition Slight pitting to the rails	Good condition	Good condition					
8900	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition	Straight Low parapets, parapets 300mm on one side and 600mm on the other				
8950		Good condition Slight pitting to the rails	Good condition	Good condition					
9000		Good condition Slight pitting to the rails	Good condition	Good condition					
9050		Good condition Slight pitting to the rails	Good condition	Good condition					
9100	Road crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
9150		Good condition Slight pitting to the rails	Good condition	Good condition	Santon Station				
9200		Good condition Slight pitting to the rails	Good condition	Good condition					
9250		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
9300	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
9350		Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
9400		Good condition Slight pitting to the rails	Good condition	Good condition					
9450		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
9500		Good condition Slight pitting to the rails	Good condition	Good condition					
9550		Good condition Slight pitting to the rails	Good condition	Good condition					
9600		Good condition Slight pitting to the rails	Good condition	Good condition					
9650		Good condition Slight pitting to the rails	Good condition	Good condition					
9700		Good condition Slight pitting to the rails	Good condition	Good condition					
9750		Good condition Slight pitting to the rails	Good condition	Good condition					
9800		Good condition Slight pitting to the rails	Good condition	Good condition					
9850		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
9900		Good condition Slight pitting to the rails	Good condition	Good condition					
9950		Good condition Slight pitting to the rails	Good condition	Good condition					
10000		Good condition Slight pitting to the rails	Good condition	Good condition					
10050		Good condition Slight pitting to the rails	Good condition	Good condition					
10100	Farm Crossing	Good condition Slight pitting to the rails	Good condition, where visible	Fair condition, contaminated with fines, moss growing on the ballast, ballast low, sleeper ends exposed.	Rail foot and web covered with ballast				
10150		Good condition Slight pitting to the rails	Good condition	Fair condition, contaminated with fines, moss growing on the ballast, ballast low, sleeper ends exposed.					
10200		Good condition Slight pitting to the rails	Good condition	Good condition					
10250	Ballalonna Level Crossing Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
10300		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
10350	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
10400		Good condition Slight pitting to the rails	Good condition	Good condition					
10450		Good condition Slight pitting to the rails	Good condition	Good condition	Straight Left Hand Curve				
10500	Road crossing	Good condition Slight pitting to the rails	Good condition	Poor condition contaminated with fines and vegetation					
10550		Good condition Slight pitting to the rails	Good condition	Good condition					
10600		Good condition Slight pitting to the rails	Good condition	Good condition					
10650		Good condition Slight pitting to the rails	Good condition	Good condition					
10700		Good condition Slight pitting to the rails	Good condition	Good condition					
10750		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
10800		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
10850		Good condition Slight pitting to the rails	Good condition	Good condition					
10900		Good condition Slight pitting to the rails	Good condition	Good condition					
10950		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
11000		Good condition Slight pitting to the rails	Good condition	Good condition					
11050		Good condition Slight pitting to the rails	Good condition	Good condition					
11100		Good condition Slight pitting to the rails	Good condition	Good condition					
11150		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
11200	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
11250		Good condition Slight pitting to the rails	Good condition	Good condition					
11300		Good condition Slight pitting to the rails	Good condition	Good condition					
11350		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
11400		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
11450		Good condition Slight pitting to the rails	Good condition	Good condition					
11500	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Fair condition,contaminated with fines from the farm crossing					
11550		Good condition Slight pitting to the rails	Good condition	Good condition					
11600		Good condition Slight pitting to the rails	Good condition	Good condition					
11650		Good condition Slight pitting to the rails	Good condition	Good condition					
11700	Underbridge Farm crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
11750		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
11800		Good condition Slight pitting to the rails	Good condition	Good condition					
11850		Good condition Slight pitting to the rails	Good condition	Good condition					
11900		Good condition Slight pitting to the rails	Good condition	Good condition					
11950		Good condition Slight pitting to the rails	Good condition	Good condition					
12000		Good condition Slight pitting to the rails	Good condition	Good condition					
12050		Good condition Slight pitting to the rails	Good condition	Good condition					
12100		Good condition Slight pitting to the rails	Good condition	Good condition					
12150	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Fair condition,contaminated with fines from the farm crossing					
12200		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
12250		Good condition Slight pitting to the rails	Good condition	Good condition					
12300	Level crossing	Good condition Slight pitting to the rails	Good condition	Poor condition,contaminated with fines from the crossing	Straight				
12350		Good condition Slight pitting to the rails	Good condition	Good condition					
12400		Good condition Slight pitting to the rails	Good condition	Good condition					
12450		Good condition Slight pitting to the rails	Good condition	Good condition					
12500		Good condition Slight pitting to the rails	Good condition	Good condition					
12550		Good condition Slight pitting to the rails	Good condition	Good condition					
12600		Good condition Slight pitting to the rails	Good condition	Good condition					
12650	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
12700		Good condition Slight pitting to the rails	Good condition	Good condition					
12750		Good condition Slight pitting to the rails	Good condition	Good condition					
12800		Good condition Slight pitting to the rails	Good condition	Good condition					
12850		Good condition Slight pitting to the rails	Good condition	Good condition					
12900		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
12950	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
13000		Good condition Slight pitting to the rails	Good condition	Good condition					
13050		Good condition Slight pitting to the rails	Good condition	Good condition					
13100		Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
13150		Good condition Slight pitting to the rails	Good condition	Good condition					
13200	Ballahick Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
13250		Good condition Slight pitting to the rails	Good condition	Good condition					
13300		Good condition Slight pitting to the rails	Good condition	Good condition					
13350		Good condition Slight pitting to the rails	Good condition	Good condition					
13400		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
13450		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
13500		Good condition Slight pitting to the rails	Good condition	Good condition					
13550		Good condition Slight pitting to the rails	Good condition	Good condition	Ballasalla Station				
13600		Good condition Slight pitting to the rails	Good condition	Good condition					
13650	Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
13700		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
13750	Footpath crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Rails are now longer and two rails have been joined by a thermic weld.				
13800		Good condition Slight pitting to the rails	Good condition	Good condition					
13850		Good condition Slight pitting to the rails	Good condition	Good condition					
13900		Good condition Slight pitting to the rails	Good condition	Good condition					
13950		Good condition Slight pitting to the rails	Good condition	Good condition					
14000		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
14050	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
14100		Good condition Slight pitting to the rails	Good condition	Good condition					
14150		Good condition Slight pitting to the rails	Good condition	Good condition					
14200		Good condition Slight pitting to the rails	Good condition	Good condition					
14250		Good condition Slight pitting to the rails	Good condition	Good condition					
14300		Good condition Slight pitting to the rails	Good condition	Good condition					
14350		Good condition Slight pitting to the rails	Good condition	Good condition					
14400		Good condition Slight pitting to the rails	Good condition	Good condition					
14450	Retaining wall	Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
14500		Good condition Slight pitting to the rails	Good condition	Good condition					
14550		Good condition Slight pitting to the rails	Good condition	Good condition					
14600		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
14650		Good condition Slight pitting to the rails	Good condition	Good condition					
14700		Good condition Slight pitting to the rails	Good condition	Good condition					
14750		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
14800		Good condition Slight pitting to the rails	Good condition	Good condition					
14850		Good condition Slight pitting to the rails	Good condition	Good condition					
14900		Good condition Slight pitting to the rails	Good condition	Good condition					
14950	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
15000		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				

Wheel rubbing the back of the switch rail

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
15050		Good condition Slight pitting to the rails	Good condition	Good condition					
15100		Good condition Slight pitting to the rails	Good condition	Good condition					
15150		Good condition Slight pitting to the rails	Good condition	Good condition					
15200		Good condition Slight pitting to the rails	Good condition	Good condition					
15250		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
15300		Good condition Slight pitting to the rails	Good condition	Good condition					
15350		Good condition Slight pitting to the rails	Good condition	Good condition					
15400		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
15450		Good condition Slight pitting to the rails	Good condition	Good condition					
15500		Good condition Slight pitting to the rails	Good condition	Good condition					
15550		Good condition Slight pitting to the rails	Good condition	Good condition					
15600		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
15650		Good condition Slight pitting to the rails	Good condition	Good condition					
15700		Good condition Slight pitting to the rails	Good condition	Good condition					
15750		Good condition Slight pitting to the rails	Good condition	Good condition					
15800		Good condition Slight pitting to the rails	Good condition	Good condition					
15850	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
15900		Good condition Slight pitting to the rails	Good condition	Good condition					
15950		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
16000		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
16050		Good condition Slight pitting to the rails	Good condition	Good condition	Castle Town Station				
16100		Good condition Slight pitting to the rails	Good condition	Good condition					
16150		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
16200		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
16250	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
16300		Good condition Slight pitting to the rails	Good condition	Good condition					
16350		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
16400		Good condition Slight pitting to the rails	Good condition	Good condition					
16450	Mill Road Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
16500		Good condition Slight pitting to the rails	Good condition	Good condition					
16550		Good condition Slight pitting to the rails	Good condition	Good condition					
16600	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
16650		Good condition Slight pitting to the rails	Good condition	Good condition					
16700		Good condition Slight pitting to the rails	Good condition	Good condition					
16750		Good condition Slight pitting to the rails	Good condition	Good condition					
16800		Good condition Slight pitting to the rails	Good condition	Good condition					
16850		Good condition Slight pitting to the rails	Good condition	Good condition					
16900		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
16950	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
17000		Good condition Slight pitting to the rails	Good condition	Good condition					
17050		Good condition Slight pitting to the rails	Good condition	Good condition					
17100		Good condition Slight pitting to the rails	Good condition	Good condition					
17150		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
17200		Good condition Slight pitting to the rails	Good condition	Good condition					
17250		Good condition Slight pitting to the rails	Good condition	Good condition					
17300	Underbridge 27	Good condition Slight pitting to the rails	Good condition	Good condition					
17350	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
17400		Good condition Slight pitting to the rails	Good condition	Good condition					
17450		Good condition Slight pitting to the rails	Good condition	Good condition					
17500		Good condition Slight pitting to the rails	Good condition	Good condition					
17550		Good condition Slight pitting to the rails	Good condition	Good condition					
17600	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
17650		Good condition Slight pitting to the rails	Good condition	Good condition					
17700		Good condition Slight pitting to the rails	Good condition	Good condition					
17750		Good condition Slight pitting to the rails	Good condition	Good condition					
17800	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
17850		Good condition Slight pitting to the rails	Good condition	Good condition					
17900		Good condition Slight pitting to the rails	Good condition	Good condition					
17950		Good condition Slight pitting to the rails	Good condition	Good condition					
18000		Good condition Slight pitting to the rails	Good condition	Good condition					
18050		Good condition Slight pitting to the rails	Good condition	Good condition					
18100		Good condition Slight pitting to the rails	Good condition	Good condition					
18150		Good condition Slight pitting to the rails	Good condition	Good condition					
18200		Good condition Slight pitting to the rails	Good condition	Good condition					
18250		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
18300		Good condition Slight pitting to the rails	Good condition	Good condition					
18350		Good condition Slight pitting to the rails	Good condition	Good condition					
18400		Good condition Slight pitting to the rails	Good condition	Good condition					
18450		Good condition Slight pitting to the rails	Good condition	Good condition					
18500		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
18550		Good condition Slight pitting to the rails	Good condition	Good condition	Ballabeg Station				
18600		Good condition Slight pitting to the rails	Good condition	Good condition					
18650		Good condition Slight pitting to the rails	Good condition	Good condition					
18700	Overbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
18750		Good condition Slight pitting to the rails	Good condition	Good condition					
18800	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
18850		Good condition Slight pitting to the rails	Good condition	Good condition					
18900		Good condition Slight pitting to the rails	Good condition	Good condition					
18950		Good condition Slight pitting to the rails	Good condition	Good condition					
19000		Good condition Slight pitting to the rails	Good condition	Good condition					
19050	Underbridge 29	Good condition Slight pitting to the rails	Good condition	Good condition					
19100		Good condition Slight pitting to the rails	Good condition	Good condition					
19150		Good condition Slight pitting to the rails	Good condition	Good condition					
19200		Good condition Slight pitting to the rails	Good condition	Good condition					
19250		Good condition Slight pitting to the rails	Good condition	Good condition					
19300		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
19350		Good condition Slight pitting to the rails	Good condition	Good condition					
19400	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
19450		Good condition Slight pitting to the rails	Good condition	Good condition					
19500	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
19550		Good condition Slight pitting to the rails	Good condition	Good condition					
19600	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
19650		Good condition Slight pitting to the rails	Good condition	Good condition					
19700		Good condition Slight pitting to the rails	Good condition	Good condition					
19750		Good condition Slight pitting to the rails	Good condition	Good condition					
19800	Underbridge 31 Farm crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
19850		Good condition Slight pitting to the rails	Good condition	Good condition					
19900		Good condition Slight pitting to the rails	Good condition	Good condition					
19950	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
20000		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
20050		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
20100		Good condition Slight pitting to the rails	Good condition	Good condition					
20150		Good condition Slight pitting to the rails	Good condition	Good condition					
20200	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
20250		Good condition Slight pitting to the rails	Good condition	Good condition					
20300		Good condition Slight pitting to the rails	Good condition	Good condition					
20350		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
20400	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
20450		Good condition Slight pitting to the rails	Good condition	Good condition					
20500		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
20550	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
20600		Good condition Slight pitting to the rails	Good condition	Good condition	Straight Switch & Crossing in this section				
20650		Good condition Slight pitting to the rails	Good condition	Good condition	Colby Station				
20700	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
20750		Good condition Slight pitting to the rails	Good condition	Good condition					
20800	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
20850		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
20900	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
20950	Farm crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
21000		Good condition Slight pitting to the rails	Good condition	Good condition					
21050	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
21100		Good condition Slight pitting to the rails	Good condition	Good condition					
21150		Good condition Slight pitting to the rails	Good condition	Good condition					
21200		Good condition Slight pitting to the rails	Good condition	Good condition					
21250		Good condition Slight pitting to the rails	Good condition	Good condition					
21300		Good condition Slight pitting to the rails	Good condition	Good condition					
21350		Good condition Slight pitting to the rails	Good condition	Good condition					
21400	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
21450		Good condition Slight pitting to the rails	Good condition	Good condition					
21500		Good condition Slight pitting to the rails	Good condition	Good condition					
21550		Good condition Slight pitting to the rails	Good condition	Good condition					
21600	Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
21650		Good condition Slight pitting to the rails	Good condition	Good condition					
21700		Good condition Slight pitting to the rails	Good condition	Good condition					
21750		Good condition Slight pitting to the rails	Good condition	Good condition					
21800		Good condition Slight pitting to the rails	Good condition	Good condition					
21850		Good condition Slight pitting to the rails	Good condition	Good condition					
21900		Good condition Slight pitting to the rails	Good condition	Good condition					
21950		Good condition Slight pitting to the rails	Good condition	Good condition					
22000	Colby Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
22050		Good condition Slight pitting to the rails	Good condition	Good condition					
22100		Good condition Slight pitting to the rails	Good condition	Good condition	Left Hand Curve				
22150		Good condition Slight pitting to the rails	Good condition	Good condition					
22200		Good condition Slight pitting to the rails	Good condition	Good condition					
22250	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
22300		Good condition Slight pitting to the rails	Good condition	Good condition					
22350	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
22400		Good condition Slight pitting to the rails	Good condition	Good condition					
22450		Good condition Slight pitting to the rails	Good condition	Good condition					
22500		Good condition Slight pitting to the rails	Good condition	Good condition					
22550		Good condition Slight pitting to the rails	Good condition	Good condition					
22600		Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
22650		Good condition Slight pitting to the rails	Good condition	Good condition					
22700		Good condition Slight pitting to the rails	Good condition	Good condition					
22750	Ballagawne Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
22800		Good condition Slight pitting to the rails	Good condition	Good condition					
22850		Good condition Slight pitting to the rails	Good condition	Good condition					
22900		Good condition Slight pitting to the rails	Good condition	Good condition					
22950		Good condition Slight pitting to the rails	Good condition	Good condition					
23000	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
23050		Good condition Slight pitting to the rails	Good condition	Good condition					
23100		Good condition Slight pitting to the rails	Good condition	Good condition					
23150		Good condition Slight pitting to the rails	Good condition	Good condition	Striaight				
23200	Underbridge	Good condition Slight pitting to the rails	Good condition	Good condition					
23250		Good condition Slight pitting to the rails	Good condition	Good condition					
23300		Good condition Slight pitting to the rails	Good condition	Good condition					
23350		Good condition Slight pitting to the rails	Good condition	Good condition					
23400	Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
23450		Good condition Slight pitting to the rails	Good condition	Good condition					
23500		Good condition Slight pitting to the rails	Good condition	Good condition					
23550	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
23600		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
23650		Good condition Slight pitting to the rails	Good condition	Good condition					
23700		Good condition Slight pitting to the rails	Good condition	Good condition					
23750	Farm Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
23800		Good condition Slight pitting to the rails	Good condition	Good condition					
23850		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
23900	Four Roads Level Crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
23950		Good condition Slight pitting to the rails	Good condition	Good condition	Four Roads Station				
24000		Good condition Slight pitting to the rails	Good condition	Good condition					
24050		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
24100		Good condition Slight pitting to the rails	Good condition	Good condition	Right Hand Curve				
24150		Good condition Slight pitting to the rails	Good condition	Good condition					
24200		Good condition Slight pitting to the rails	Good condition	Good condition					
24250		Good condition Slight pitting to the rails	Good condition	Good condition					
24300		Good condition Slight pitting to the rails	Good condition	Good condition	Straight				
24350	Footpath crossing	Good condition Slight pitting to the rails	Good condition	Good condition					
24400		Good condition Slight pitting to the rails	Good condition	Good condition					
24450		Good condition Slight pitting to the rails	Good condition	Good condition					
24500		Good condition Slight pitting to the rails	Good condition	Good condition					

IoMR Track Condition Report

Metres	Features	Rail condition	Sleeper condition	Ballast condition	Other comments	Rails	Joists	Sleepers	Ballast
24550		Good condition Slight pitting to the rails	Good condition	Good condition					
24600		Good condition Slight pitting to the rails	Good condition	Good condition					
24650		Good condition Slight pitting to the rails	Good condition	Good condition					
24700		Good condition Slight pitting to the rails	Good condition	Good condition					
24750		Good condition Slight pitting to the rails	Good condition	Good condition					
24800	Level crossing	Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
24850		Good condition Slight pitting to the rails	Good condition	Good condition	Switch & Crossing in this section				
24900		Good condition Slight pitting to the rails	Good condition	Good condition					
24950		Good condition Slight pitting to the rails	Good condition	Good condition					
25000		Good condition Slight pitting to the rails	Good condition	Good condition					
25050		Good condition Slight pitting to the rails	Good condition	Good condition					
25100		Good condition Slight pitting to the rails	Good condition	Good condition					
25150		Good condition Slight pitting to the rails	Good condition	Good condition					
25200		Good condition Slight pitting to the rails	Good condition	Good condition	Port Erin Station				
25250		Good condition Slight pitting to the rails	Good condition	Good condition					
25300		Good condition Slight pitting to the rails	Good condition	Good condition					
25350		Good condition Slight pitting to the rails	Good condition	Good condition	Buffer Stops				