



**Isle of Man
Government**

Douglas (Summerhill)

Douglas (Central)

Douglas (Broadway)

Laxey

Ramsey

Peel

Port Erin

Port St. Mary

Castletown

Derbyhaven

Kirk Michael (Balleira)

Port Soderick

Bay-ny-Carrickey

Jurby


Fenella Beach (Peel)

Garwick

BATHING WATER QUALITY 2006

Water at the beaches below is tested regularly for cleanliness according to standards laid down in EC Bathing Water Directive. Results are shown as follows under a scheme devised by the Department of Local Government and the Environment.


EXCELLENT 

GOOD 

POOR 

Past Results			
Y	E	A	R
02	03	04	05
FAIL	PASS	FAIL	PASS
PASS	FAIL	FAIL	PASS
PASS	PASS	PASS	PASS
PASS	PASS	PASS	FAIL
PASS	FAIL	FAIL	PASS
PASS	PASS	FAIL	PASS
FAIL	PASS	PASS	PASS
PASS	PASS	PASS	PASS
PASS	PASS	PASS	PASS
FAIL	FAIL	FAIL;	FAIL
PASS	PASS	PASS	PASS
FAIL	FAIL	FAIL	FAIL
PASS	PASS	FAIL	PASS
PASS	PASS	PASS	FAIL
FAIL	FAIL	FAIL	FAIL

Day	10-11	17-18	24-25	31/1	7-8	14-15	21-22	28-29	3-4	12-13	19-20	26-27	1-2	9-10	16-17	23-24	30-31	6-7	13-14	19/21
Month	5	5	5	5/6	6	6	6	6	7	7	7	7	8	8	8	8	8	9	9	9



Excellent water quality means the weekly sample meets following EC Guideline standards:

500 total coliforms per 100ml of water and 100 faecal coliforms per 100ml of water.
Annually 80% of samples taken must meet these standards.

Good water quality means the weekly sample meets the following EC Mandatory standards:

10,000 total coliforms per 100ml of water and 2,000 faecal coliforms per 100ml of water.
Annually 95% of samples taken must meet these standards.

Poor water quality indicates the sample failed to meet the standards required for Good quality waters.



For further details contact:
The Government Laboratory
Ballakermeen Road
Douglas

IM1 4BR
Tel: 642335
E Mail: govlab@gov.im

NT Not Tested